

Safety Package TiMix

[No product image available](#)

Description

The speed of both motor and shaker is continuously monitored.

In case of deviations, e.g. due to a defective drive belt, a warning message is displayed and an acoustic signal is audible.

Details

Order No.: 0060 022